



1/6



**FIG. 1
(PRIOR ART)**



**FIG. 2
(PRIOR ART)**

2/6




FIG. 3

<u>26a</u>	<u>27b</u>	<u>27b</u>	<u>27b</u>	<u>26c</u>
<u>27a</u>	<u>28</u>	<u>28</u>	<u>28</u>	<u>27c</u>
<u>27a</u>	<u>28</u>	<u>28</u>	<u>28</u>	<u>27c</u>
<u>26b</u>	<u>27d</u>	<u>27d</u>	<u>27d</u>	<u>26d</u>



FIG. 4

3/6




FIG. 5

FIG. 6





FIG. 7

4/6




FIG. 8

Growth of amorphous or polycrystalline sensor material




FIG. 9





FIG. 10

5/6



6/6




FIG. 12